


[illegible]

11-11-11

A schematic diagram of a mechanical assembly. It features two large rectangular blocks, labeled 14 and 18, positioned on a horizontal surface. A zigzag member, labeled 20, is connected to the top of block 14 and the top of block 18. An arrow, labeled 12, points to the right-hand side of the zigzag member 20.

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

00627-9049260

FIG. 8




FIG. 9




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 10D




FIG. 10E

00021 9025260



FIG. 12A




FIG. 12B





FIG. 12C





006277 90252/60




FIG. 13

09726706.11900




FIG. 14